An X1600 128mb PCI-e onboard.

The new OS X is being released in 9 days (apple.com) and i've got it on preorder, so i'll probably be forced to do a fresh install of windows which will be fine anyway since it's acting up like it's infected (i press a key, no response, just happened today after the blue screen of death).

EDIT It's an ATI card... not Mac specific since it runs on Intel chipsets now...

Even though... why the fuck did it install faulty software in the first place?