Subject: Slow Vid Card...
Posted by Bearxor on Sun, 31 Aug 2003 13:44:13 GMT
View Forum Message <> Reply to Message

General HavocMainly the KT400 board as I don't use the KT333 ones much now. It seems to effect the FX 5600. I had a lod of the KT400 boards that had a faulty BIOS setting so they need upgrades to enable the 8x AGP. It seemed to fix the problems with the FX 5600 after.

Yea, when the KT400 boards first hit the market they didn't work with 8X AGP cards correctly. Thats why I hate adopting early. We never carried KT400 boards... We held out for NF2 boards.