
Subject: Re: Motherboards.....Again

Posted by [nikki6ixx](#) on Thu, 01 Jul 2010 04:55:35 GMT

[View Forum Message](#) <> [Reply to Message](#)

I decided to play around with my 955 for a bit today. I upped the multiplier to 19.5, and set my CPU voltage to 1.5. So that's 3.9GHz, and it ran 'stable' in Prime95 for a half hour or so; I wouldn't call that totally stable unless it ran for about 6 hours, though.

My CPU has C2 stepping, so getting it to 4.0GHz is pretty tough. Your 955 may have C3 stepping and those are able to surpass that barrier more easily. Chances are, a C3 CPU may need less voltage to get to the same spot as mine has.
